

मुख्य अग्निशमन अधिकारी
OFFICE OF THE CHIEF FIRE OFFICER
अण्डमान तथा निकोबार द्वीप समूह
Andaman and Nicobar Islands

Clearance Number : **FS/FCC/2024/1395**

Port Blair dated **30/06/2024**

FIRE CLEARANCE CERTIFICATE

This is to certify that the **NIRMALA SENIOR SECONDARY SCHOOL** situated at **PREM NAGAR, P.O HADDO ,PREM NAGAR ,PORT BLAIR** bearing Survey No. **33/1**. have complied with the fire prevention and fire safety requirements in accordance with NBC guidelines and verified by Fire Brigade Officer on **19/06/2024** and the school is safe from fire safety point of view for a period of one (1) year from the date of issue of this FCC, subject to compliance of specific conditions as appended:-

Note:- Conditions for the validity of Fire Clearance Certificate(FCC)

1. The school comprised of six blocks connected to each other in different level. The administrative block, block-I, block-II, block-III & block-V are having G+2 floors and block-IV is having G+1 floor for functioning of classes from KG -II to XII standard.
2. Building stability and satisfactory electrical installation to be ascertained from concerned agency.
3. FCC shall stand null and void if there is any violation in existing firefighting arrangements.
4. FCC may not be treated in any case for regularization of unauthorized construction, if any or violation in building plan.
5. All fire safety arrangements provided therein shall be maintained in good working conditions at all time and all staff members shall be well acquainted to operate all fire safety equipments.
6. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
7. All staff should be trained in firefighting. Trained firefighting staff should be available round the clock.
8. Any deviation with regard to construction etc. shall be verified by the

concerned building sanctioning authority.

9. Means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.

10. Occupant load in class room should be calculated at not less than 4 m² floor area per students.

11. Occupant load of Auditorium at first floor of block-IV should be calculated at not less than 1.4 sqm floor area per student. The students from pre-primary to Class I should not be assembled in Auditorium.

12. Classes from pre-primary to 1st Standard should be at ground floor only.

14. The firefighting equipment register, mock drill register and staff training register should be updated regularly.

Copy to:-

1. The Secretary, PBMC, P/Blair for kind information
2. The Director of Education, P/Blair for kind information



Inspector Fire Brigade (Port Blair)
Andaman and Nicobar
Islands

To

FR. ARUN KUMAR
TIRKEY
PREM NAGAR, P.O
HADDO
PREM NAGAR
PORT BLAIR
SOUTH ANDAMAN -
744102

